	KING COUN	INTERNATIONAL AIRPORT INCI	report /	
INCIDENT:		DATE OCCURRED 05-04-92	DATE REPORTED	
FUEL SPILL		TIME OCCURRED 1651 hours	TIME REPORTED	
LOCATION(S) OF OCC	URRENCE:			
South Flightc	raft Hangar ramp	)		
REPORTED BY:		PHONE NO(S):		
On View				
SUMMARY:				

Officer Sawyer observed a liquid leaking out of the bottom of Turbo Commander N512JD parked at the south Flightcraft hangar ramp. A large amount of liquid was running down the ramp toward a drain. It was determined that it was Jet A fuel and Officer Sawyer requested that the aviation department of South Seattle Community College be contacted since it was one of their aircraft. Jim Morefield and Bernie Paholke arrived and discovered that due to the heat (85°+) the fuel cells had burst. The aircraft was last checked by them at 1500hours. Fuel was dripping throughout the fueselage, avionics, and passenger compartment. While they borrowed siphoning equipment from Flightcraft and siphoned approximetly 150+ gallons to drain the tanks, Officer Sawyer washed down the spill with about 6 tankfuls of water and 3 gallons of Cejer in FD#2. It is estimated that 50 gallons of Jet A fuel went down the drain along with the wash down water and Cejer. The scene was secured at 1957hrs.